

# Free PDF Quiz High Hit-Rate HP - HPE6-A86 - Test HPE Network Switching Associate Exam Pdf

Pass HP HPE6-A86 Exam | Latest HPE6-A86 Dumps & Practice Exams - Cert007

---

**Exam** : **HPE6-A86**

**Title** : HPE Network Switching  
Associate Exam

<https://www.cert007.com/exam/hpe6-a86/>

---

1 / 4

2026 Latest Exam4PDF HPE6-A86 PDF Dumps and HPE6-A86 Exam Engine Free Share: <https://drive.google.com/open?id=1QaKsNKKiYjp1Y7gw60eb4lZYbxm2t7r>

Elementary HPE6-A86 practice materials as representatives in the line are enjoying high reputation in the market rather than some useless practice materials which cash in on your worries. We can relieve you of uptight mood and serve as a considerate and responsible company which never shirks responsibility. It is easy to get advancement by our HPE6-A86 practice materials. On the cutting edge of this line for over ten years, we are trustworthy company you can really count on.

As you can find on our website, we have three versions of our HPE6-A86 learning questions: the PDF, Software and APP online. The online test engine and window software need to run on computers. The PDF version of the HPE6-A86 training engine is easy to make notes. In short, all of the three packages are filled with useful knowledge. You can try our free trails before making final decisions since we also have demos of our HPE6-A86 Exam Materials for you to free download before your payment.

**>> Test HPE6-A86 Pdf <<**

## Use HPE6-A86 Exam Questions - Best Way To Get Success

Once you get the HP HPE6-A86 certificate, you can quickly quit your current job and then change a desirable job. The HP HPE6-A86 certificate can prove that you are a competent person. So it is easy for you to pass the interview and get the job. The assistance

of our HPE6-A86 practice quiz will change your life a lot.

## HPE Network Switching Associate Exam Sample Questions (Q80-Q85):

### NEW QUESTION # 80

A Support Technician is troubleshooting a problem where a new VoIP phone is not turning on when connected to port 1/1/10 of an AOS-CX switch. The technician needs to verify if the switch is providing Power over Ethernet (PoE) to the port and check its status.

show power-over-ethernet interface 1/1/10

Status and Counters - Port Power Status for port 1/1/10 Power Enable : Yes PoE Port Status : Searching

...

Detection Status : Searching

Based on the output, what is the most likely issue?

- A. The port is administratively disabled.
- **B. The VoIP phone connected to the port is not a PoE-capable device or has failed.**
- C. The port's PoE priority is configured too low.
- D. The switch has insufficient power in its PoE budget.

**Answer: B**

### NEW QUESTION # 81

On a switched infrastructure using Spanning Tree, what entity defines the best path for traffic in an HPE Aruba Networking CX environment?

- **A. Root bridge**
- B. Alternative bridge
- C. Designated bridge
- D. Common bridge

**Answer: A**

Explanation:

The correct answer is A. Root bridge. In a switched infrastructure using Spanning Tree Protocol, the root bridge is the central reference point for calculating the loop-free Layer 2 topology. HPE Aruba Networking AOS-CX documentation explains that device roles, such as root bridge or leaf node, should be planned by adjusting spanning tree instance priority. It also notes that the placement of root bridges is important in a Layer 2 network domain because deterministic root and secondary root bridges provide predictability and protection. Switches calculate their best path toward the root bridge based on spanning tree information such as bridge priority, path cost, and port roles. This calculation determines which ports forward and which ports block to prevent loops. Option B is incorrect because a designated bridge or designated port forwards traffic for a segment but does not define the overall topology reference point. Option C is incorrect because "alternative bridge" is not the entity that defines best path selection. Option D is incorrect because "common bridge" is not the correct STP role.

### NEW QUESTION # 82

Which of the statements is true about Rapid Spanning Tree Protocol (RSTP)? (Select two)

- **A. It has a faster convergence time than STP.**
- **B. It supports only a single spanning tree instance.**
- C. It uses the same port roles and states as STP.
- D. It operates on a per-VLAN basis.

**Answer: A,B**

### NEW QUESTION # 83

Which are true about VSF stacking? (Select two)

- A. AOS-CX and AOS-S switches can be mixed in a VSF stack.
- B. Different models of CX 6200 Series can be mixed in a VSF stack.
- C. CX 6200 Series and CX 6300 Series can be mixed in a VSF stack.
- D. CX 8325 Series VSF stack supports up to 10 switches.
- E. The use of VSF is recommended in the access layer of a campus network.

Answer: B,E

#### NEW QUESTION # 84

A newly connected 500R series access point is not visible in HPE Aruba Networking Central. You have run the following commands to troubleshoot.

```

interface vlan10
  description Infrastructure Management
  ip address 10.80.10.1/24
  ip helper-address 10.200.10.51
  exit

access-1#show run int 1/1/1
interface 1/1/1
  no shutdown
  description Access Point
  vlan trunk native 10
  vlan trunk allowed 10,20,30
  exit

access-1#show lldp neighbor-info 1/1/1
port : 1/1/1
neighbor Entries : 1
neighbor Entries Deleted : 0
neighbor Entries Dropped : 0
neighbor Entries Aged-Out : 0
neighbor System-Name : b8:37:b2:5f:21:21
neighbor System-Description : ArubaOS (MODEL: AP-505R ), Version Aruba IA
neighbor Chassis-ID : b8:37:b2:5f:21:21
neighbor Management-Address : 169.254.2.58
chassis Capabilities Available : Bridge, WLAN
chassis Capabilities Enabled : WLAN
neighbor Port-ID : b8:37:b2:5f:21:21
neighbor Port-Desc : eth0

```

Based on the output, what could be the problem?

- A. The DHCP server is not available
- B. The DHCP server must be in the same subnet as the AP
- C. The AP does not support DHCP
- D. The switch port should be configured as an access port

Answer: A

Explanation:

The access point is advertising a 169.254.x.x address, which indicates it did not receive an address from DHCP. This points to DHCP not being reachable or not providing leases for the management VLAN used by the AP.

#### NEW QUESTION # 85

.....

The HPE6-A86 certification exam is essential for future development, and the right to a successful HPE6-A86 exam will be in your own hands. As long as you pass the exam, you will take a step closer to your goal. However, unless you have updated HPE6-A86 exam materials, or passing the exam's mystery is quite challenging. Thousands of people tried the HPE6-A86 exams, but despite having good professional experience and being well-prepared, the regrettable exam failed. One of the main reasons for the failure may be that since practice and knowledge alone are not enough, people need to practice our Exam4PDF HPE6-A86 Exam Materials, otherwise they cannot escape reading. Well, you are in the right place. The HPE6-A86 questions on our Exam4PDF are one of the most trustworthy questions and provide valuable information for all candidates who need to pass the HPE6-A86 exam.

Exam HPE6-A86 Course: <https://www.exam4pdf.com/HPE6-A86-dumps-torrent.html>

Through the assessment of your specific situation, we will provide you with a reasonable schedule, and provide the extensible version of HPE6-A86 exam training you can quickly grasp more knowledge in a shorter time, Please purchase one kind of HPE6-A86 valid

