


# 100% Pass 2026 Trustable ITFAS-Level-1: Latest Inspection and Testing of Fire Alarm Systems Level I Exam Training



BTW, DOWNLOAD part of Exam4Tests ITFAS-Level-1 dumps from Cloud Storage: <https://drive.google.com/open?id=1NO10SZzB9XYkrT3mWtXpiK7gZEWscsNU>

First and foremost, we have high class operation system so we can assure you that you can start to prepare for the ITFAS-Level-1 exam with our study materials only 5 to 10 minutes after payment. Second, once we have compiled a new version of the ITFAS-Level-1 test question, we will send the latest version of our ITFAS-Level-1 Training Materials to our customers for free during the whole year after purchasing. Last but not least, our worldwide after sale staffs will provide the most considerate after sale service for you in twenty four hours a day, seven days a week.

You can also trust Exam4Tests NICET ITFAS-Level-1 exam questions and start this journey with complete peace of mind and satisfaction. The Inspection and Testing of Fire Alarm Systems Level I Exam practice questions are designed and verified by experienced and qualified Inspection and Testing of Fire Alarm Systems Level I Exam (ITFAS-Level-1) exam experts. They work collectively and put their expertise to ensure the top standard of Exam4Tests NICET ITFAS-Level-1 Exam Dumps. So we can say that with the Exam4Tests NICET ITFAS-Level-1 exam questions, you will get everything that you need to learn, prepare and pass the difficult NICET ITFAS-Level-1 certification exam with good scores.

>> Latest ITFAS-Level-1 Training <<

## Pdf ITFAS-Level-1 Dumps - Test ITFAS-Level-1 Simulator Online

If you are determined to get the certification, our ITFAS-Level-1 question torrent is willing to give you a hand; because the study materials from our company will be the best study tool for you to get the certification. Now I am going to introduce our ITFAS-Level-1 Exam Question to you in detail, please read our introduction carefully, we can make sure that you will benefit a lot from it. If you are interest in it, you can buy it right now.

## NICET Inspection and Testing of Fire Alarm Systems Level I Exam Sample Questions (Q77-Q82):

### NEW QUESTION # 77

Load testing of the control unit's VRLA batteries reveals that they must be replaced. Which two of the following are requirements for the replacement of VRLA batteries? (Choose two.)

- A. Batteries shall be approved by the authority having jurisdiction.
- B. Batteries shall be the same make and model as those being replaced.
- C. Batteries shall be listed by a nationally recognized testing laboratory.
- D. Batteries shall be marked with the month and year of manufacture.

**Answer: C,D**

Explanation:

Replacement batteries used in fire alarm systems must meet strict safety and documentation requirements:

NFPA 72 (2022), Section 10.6.10.1.2:

"Batteries shall be marked with the month and year of manufacture."

NFPA 72 (2022), Section 10.6.10.2:

"Batteries shall be listed for the intended purpose by a nationally recognized testing laboratory (NRTL)." There is no requirement that replacement batteries must be the same make/model, though compatibility must be ensured.

Correct answers:

- \* Batteries shall be listed by a nationally recognized testing laboratory
- \* Batteries shall be marked with the month and year of manufacture

### NEW QUESTION # 78

The fire alarm control unit shows a supervisory signal on the display. What is the possible cause?

- A. A duct smoke detector is in alarm.
- B. A spot smoke detector is in alarm.
- C. A waterflow alarm has been activated.
- D. A manual fire alarm box has been activated.

**Answer: C**

Explanation:

A supervisory signal indicates a condition that requires attention but is not an alarm. In sprinkler systems, one of the most common supervisory signals comes from a valve tamper switch, indicating a partially closed valve, or sometimes a waterflow switch reset issue.

NFPA 72 (2022), Section 3.3.2.6.9:

"Supervisory Signal - A signal indicating the need for action in connection with the supervision of guard tours, the fire suppression systems, or equipment or maintenance features of related systems." Also: Table A.10.14.2.1 Shows that waterflow valves and tamper switches are typical sources of supervisory signals.

So the correct answer - a waterflow alarm implies something abnormal with the fire protection system, possibly indicating a tamper switch or system supervisory issue.

Correct answer: D. A waterflow alarm has been activated

### NEW QUESTION # 79

Smoke alarms in one- and two-family dwellings shall be replaced when they fail to operate or they have been in place a maximum of how many years?

- A. 0
- B. 1
- C. 2
- D. 3

**Answer: A**

Explanation:

NFPA 72 requires smoke alarms in residential settings to be replaced every 10 years, even if they have not shown any signs of failure.

NFPA 72 (2022), Section 29.8.1.4:

"Unless otherwise recommended by the manufacturer, smoke alarms shall be replaced when they fail to respond to operability tests

or have been in service for 10 years." Correct answer: C. 10

#### NEW QUESTION # 80

How frequently should control equipment for a fire alarm system that is unmonitored for alarm, supervisory, and trouble signals be visually inspected?

- A. Annually
- B. Weekly
- C. Daily
- D. Semiannually

**Answer: C**

Explanation:

NFPA requires daily visual inspection of fire alarm control equipment if it is not monitored (not connected to a supervising station). This is to manually check for trouble lights, alarms, or other fault indications.

NFPA 72 (2022), Table 14.3.1 - Control Equipment (not monitored):

Visual inspection frequency: Daily

Correct answer: A. Daily

#### NEW QUESTION # 81

The flash rate of visible notification appliances shall be a minimum of how many flashes per second?

- A. 0
- B. 1
- C. 2
- D. 3

**Answer: C**

Explanation:

Visible notification appliances (strobes) must flash at a minimum rate of one flash per second to meet visibility and perceptibility requirements.

NFPA 72 (2022), Section 18.5.3.4.1:

"The flash rate shall be not less than 1 flash per second and not more than 2 flashes per second." Correct answer: A. 1

#### NEW QUESTION # 82

.....

Our ITFAS-Level-1 exam reference materials allow free trial downloads. You can get the information you want to know through the trial version. After downloading our ITFAS-Level-1 study materials trial version, you can also easily select the version you like, as well as your favorite ITFAS-Level-1 exam prep, based on which you can make targeted choices. Our ITFAS-Level-1 Study Materials want every user to understand the product and be able to really get what they need. Our ITFAS-Level-1 study materials are so easy to understand that no matter who you are, you can find what you want here.

**Pdf ITFAS-Level-1 Dumps:** <https://www.exam4tests.com/ITFAS-Level-1-valid-braindumps.html>

Pdf ITFAS-Level-1 Dumps - Inspection and Testing of Fire Alarm Systems Level I Exam VCE is the latest, valid and accurate study material for candidates who are eager to clear exams, NICET Latest ITFAS-Level-1 Training Free Demo to Download, As an adult or a student, I believe you are quite familiar with the point that maybe you will encounter what you are to be tested in the exam when you go through ITFAS-Level-1 exam pdf cram originally designed for it, NICET Latest ITFAS-Level-1 Training Time is money, time is life.

Which Google manager would have imagined people Latest ITFAS-Level-1 Training substituting Facebook for Gmail, There's no more fitting symbol for the game of golf than a circle, Inspection and Testing of Fire Alarm Systems Level I Exam VCE is the latest, Dumps ITFAS-Level-1 Free Download valid and accurate study material for candidates who are eager to clear exams.

### Quiz 2026 ITFAS-Level-1: High-quality Latest Inspection and Testing of Fire

<https://drive.google.com/open?id=1NO10SZzB9XYkrT3mWtXpiK7gZEWscsNU>