


# International Code Council M2 Test Passing Score | M2 Reliable Exam Questions



Experts at TestPDF strive to provide applicants with valid and updated International Code Council M2 exam questions to prepare from, as well as increased learning experiences. We are confident in the quality of the International Code Council M2 preparational material we provide and back it up with a money-back guarantee. TestPDF provides International Code Council M2 desktop-based practice software for you to test your knowledge and abilities. The M2 desktop-based practice software has an easy-to-use interface.

Our M2 questions answers study guide is the best option for you to pass exam easily. Our experts are busy in providing the most updated content that could ensure your 100% success in M2 actual test. The up-to-date International Code Council exam dumps consist of latest practice questions answers and explanations. We are devoted to take appropriate steps in improving our products like M2 Pass Guide.

>> International Code Council M2 Test Passing Score <<

## 2026 M2 Test Passing Score: Commercial Mechanical Inspector - Latest International Code Council M2 Reliable Exam Questions

The learning material is available in three different easy-to-use forms. The first one is a PDF form. The students can save the M2 questions by taking out their prints or can access them on their smartphones, tablets, and laptops. The PDF form can be used anywhere anytime and is essential for applicants who like to learn from their smart devices. The second form is Commercial Mechanical Inspector (M2) web-based practice test which can be taken from browsers.

### International Code Council Commercial Mechanical Inspector Sample Questions (Q44-Q49):

#### NEW QUESTION # 44

Solid-fuel cooking equipment:

- A. is permitted to be installed under Type II canopy-type hoods.
- B. is permitted to be installed under common canopy-type hoods with other cooking equipment.
- **C. shall be vented through a separate hood and exhaust system**
- D. is permitted to be installed under Type II noncanopy-type hoods.

**Answer: C**

Explanation:

Solid-fuel cooking equipment requires a separate hood and exhaust system. It is not permitted to share the same hood/exhaust arrangement in the manner suggested by the other choices. This is a standard commercial kitchen exhaust requirement because of the added fire and residue hazards associated with solid-fuel appliances.

#### NEW QUESTION # 45

An 8-inch Type B venting system with a listed vent cap must terminate a minimum of \_\_\_\_\_ feet above the flat roof through which it passes.

- A. 0
- B. 1
- C. 2
- D. 3

**Answer: A**

Explanation:

For a Type B gas vent with a listed vent cap terminating through a flat roof, the minimum required termination height is 1 foot above the roof. That makes Option A correct. This is consistent with gas vent termination tables used with listed Type B vent systems and the code framework for Type B vent terminations.

#### NEW QUESTION # 46

Termination of vents for appliances listed for and installed outdoors that incorporate integral venting shall:

- A. terminate not less than 5 feet vertically above the lowest connected appliance draft hood outlet or flue collar.
- B. be installed in accordance with the design professional's plans as approved by the local building official.
- C. be installed in accordance with their listings and the manufacturer's installation instructions.
- D. terminate not less than 5 feet vertically above the highest connected appliance draft hood outlet or flue collar.

**Answer: C**

Explanation:

For appliances listed for outdoor installation and incorporating integral venting, the IMC requires them to be installed in accordance with their listings and the manufacturer's installation instructions. That matches Option C exactly.

#### NEW QUESTION # 47

Which of the following is not a required mechanical inspection?

- A. Final
- B. Annual system test
- C. Underground
- D. Rough-in

**Answer: B**

Explanation:

The ICC mechanical administrative inspection sequence includes underground inspection, rough-in inspection, and final inspection as required inspections. An annual system test is not listed as one of the required permit inspections in that section, so Option B is the correct answer. This fits the M2 General Administration content area, which includes permit and inspection administration.

#### NEW QUESTION # 48

The minimum size for access openings for fire dampers shall be:

- A. one-half the diagonal of the access opening.
- B. the same as the dimension of the duct.
- C. 12 inches by 12 inches.

